

ItemID	Module	Sub-Module	Description
2.1034	Logbook	Data	Selecting a new Callsign or Country must update the Location fields.
2.1092	Logbook	Standalone	Having stopped tracking of freq, band & mode it is not persistent when the ALE window is closed and re-opened
2.1093	Logbook	Standalone	Clicking on a DX spot enters the stations details OK but does not enter the frequency and band into the ALE window
3.1005	HRD	Radio Support	Kenwood TS2000 menu #28a shows a setting of 2 when in reality the setting is OFF. When the setting is changed and re-downloaded the menus, menu displays a red X and also the setting displays "unknown (2) 2.
3.1017	HRD	Radio Support	Added missing Tune button for TS2000
4.1032	DM780	Winkeyer	Winkeyer window becomes inaccessible if auto connect is used
4.1033	DM780	Various	Extra lne feed problem in RTTY mode